



SECTIUNE TRANSVERSALA 3-3

Scara 1:50




DETALIU DE SCARA

Scara 1:20




DETALIU TREAPTA DIN BETON PREFABRICAT

Sc 1:10




DETALIU CASIU PE TALUZ

Scara 1:50




SECTIUNE A-A

Scara 1:20



DETALIU CASIU


Scara 1:20



CERINTE DE CALITATE:

Beton: C12/15 C16/20 C25/30
Clasa de expunere: 2a
Grad de impermeabilitate: P8¹⁰
Grad de gelivitate: G150
Tip de ciment: I 42.5(R)
Valoare maxima A/C: 0.45

Clasa "E" de incarcare - A30, V80
Categoriza de importanta privind calitatea "B" (deosebita)
Exigenta de calitate A4,B2,D2
Zonare seismica conform P100/2006 :
Ks=0.16, Tc=1.0s pt. IMR=100ani



S.C. VORA S.R.L. CODLEA J08/1747/2003			Denumire proiect: REPARAȚIE POD DN 1 km 138+850 Loc. Predeal, Jud. Brașov	FAZA : D. E.
Beneficiar: C.N.A.D.N.R. - D.R.D.P. BRAȘOV			PROIECT NR. 95A/2011	
Proiectat ing Catalin Gafton	Desenat ing Catalin Gafton	Verificat ing. Marius Comanici	Scara: 1:10, 1:20 1:50 02/2012	PLANSA NR. SC1